

We Do The Job **RIGHT!**

- AC coils steam cleaned.
- Refrigeration coils steam cleaned.
- Exhaust fan steam cleaned.
- Sidewalls cleaned.
- Dumpster's cleaned.
- Loading docks cleaned.
- Awnings cleaned.



Let Us Solve  
Your Vent Hood  
Grease & Smoke  
Problem


Boston Powerwash  
P.O. Box 281  
Scituate, MA 02066  
(781) 888-5100

City of Boston Certified

## GREASE & SMOKE START HERE

Problem start on the cooking surface. Grease, smoke and fatty acids are produced by the heat of cooking on a grill.

1. Grease and Smoke particles are drawn up into the system filters.
2. Range Hood contains the Filters.
3. Vapors are drawn through Vent-Hood System...
4. Up the main duct work...
5. To the roof line...
6. Into the exhaust fan and onto the roof.



## Result: Four Major Problems

The result can be as obvious as fire damage and roof deterioration, or as concealed as nasty grease colors.

- **FIRE HAZARD** • Fire is your worst nightmare. Dangerous, life threatening, and very very expensive.
- **SANITARY HAZARD** • The smell of rancid grease repels customers and attracts Health and Fire Department Inspectors.
- **ROOF DECAY** • Equals roof replacement... A costly time consuming result.
- **EXHAUST FAN FAILURE** • Grease build up causes fan malfunction and motor burn out. Very expensive to replace.

## The Solution?

**Complete Exhaust System Degreasing.**

Boston Vent-A-Clean has the number one cleaning system in the industry, combining the **Best Cleaning Techniques** with **State of the Art Equipment** and **Chemicals**.

B.P. Employees are covered by General Liability Insurance.

The B.P. Guarantee: We will leave your exhaust system and Kitchen clean and in good working order.

Vent-A-Clean

We Do The Job Right!!